



ROVVER 400 Video Inspection Robot



Failed joint in drain line running from WEDF to PBF-16 leach pond.





Elbow leading to out-of-service drain in WEDF.